



Air Gage Readout Service Policy

Clean and Report Service

Standard clean and report service for all readouts is available at our listed prices:

Western Gage Readouts.....	\$325.00*
Add for each additional channel.....	\$115.00
Other Manufacturers Readouts.....	\$395.00
Minimum Inspect Charge...WGC.....	\$115.00**
....Other Mfg... ..	\$150.00**

* Applies to WGC Single Channel Readouts

**Will waive if repair or replacement is purchased

Contact a WGC Sales associate for details on ISO17025 Calibration services.

Repair Services

Fully Supported WGC Readouts

Parts and extra labor charges required to repair WGC Supported units will be provided to the customer after inspection; a PO incorporating any additional charges will be required before repair of the unit. If a WGC Supported unit is not repairable, a \$115.00 inspection fee will be charged. The inspection fee will be waived if a new readout is purchased on the same PO.

Inspection Fee (non-repairable units)..... \$115.00

WGC Legacy and Other Manufacturer Readouts

Western Gage may not be able to offer repair services on Legacy Readouts or readouts from other manufacturers as many essential components are no longer readily available to support these repairs. **Repairs are subject to available parts.

WGC Fully Supported Readouts	
Micro IIz	
Micro II	
AEK II	
WGC Legacy Readouts	
L-10	ACH
H-37	Micro Air
H-100	AEK
ACL	**Millicheck

Readout Service Matrix			
	WGC Full Support	WGC Legacy	Other Mfg.
Inspect	\$115	\$115	\$150
Clean & Report	\$325 + \$115 ea. additional channel		\$395 + \$115 ea. add'l ch.
Repair	P & L	N/A	N/A
Replace	Waive \$115 inspection Fee with purchase on same PO	Waive \$115 minimum Fee with purchase on same PO, WGC recycles old Readout	Waive \$150 minimum Fee with purchase on same PO, WGC recycles old Readout